



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

Nixon O

Patent No.: 6,770,860 B1 Serial No.: 09/782,035

February 14, 2001 Issued: August 3, 2004 Filed:

Title: DUAL LINE INTEGRATING LINE SCAN SENSOR

PETITION FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 C.F.R. § 1.322 OR § 1.323

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Certificate

FFB 2 2 2005

Sir:

Patentee hereby requests that the above-identified U.S. patent be corrected in accordance with the attached Certificate of Correction.

I. C.F.R. § 1.322

 \boxtimes The mistake was incurred through the fault of the Patent and Trademark Office and is clearly disclosed in the records of the Office. Therefore, no fee is due.

II. C.F.R. § 1.323

The mistake was made by patentee. Therefore, a check in the amount of \$100.00 in payment of the fee set forth in 37 C.F.R. § 1.20(a) is enclosed herewith.

Enclosed herewith is a Form PTO-1050 (in duplicate) listing an error that has been found in the above-identified patent. The error is of a clerical or typographical nature or of

FEB 2 3 2005

minor character and was made in good faith. The requested correction does not constitute new matter or require reexamination.

III. Accordingly, patentee and their assignee respectfully request that the Patent and Trademark Office issue a Certificate of Correction pursuant to 37 C.F.R. § 1.322 or § 1.323, respectively.

Respectfully submitted,

Daniel E. Fisher, Reg. No. 34,162

Attorney for Patentees

MILLEN, WHITE, ZELANO & BRANIGAN, P.C.
Arlington Courthouse Plaza 1, Suite 1400 2200 Clarendon Boulevard
Arlington, Virginia 22201
Telephone: (703) 243, 6333

Telephone: (703) 243-6333 Facsimile: (703) 243-6410

Attorney Docket No.: DALSAINC-0028

Date: February 16, 2005

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO .:

6,770,860 B1

DATED:

August 3, 2004

INVENTOR(S):

Nixon O

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 7, line 40, "alone" should read --along--.

MAILING ADDRESS OF SENDER: Millen, White, Zelano & Branigan, P.C. 2200 Clarendon Blvd., Suite 1400

Arlington, VA 22201

PATENT NO. 6,770,860 B1

No. of additional copies

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Commissioner of Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO .:

6,770,860 B1

DATED:

August 3, 2004

INVENTOR(S):

Nixon O

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 7, line 40, "alone" should read --along--.

MAILING ADDRESS OF SENDER: Millen, White, Zelano & Branigan, P.C. 2200 Clarendon Blvd., Suite 1400

PATENT NO. 6,770,860 B1

Arlington, VA 22201

No. of additional copies